

SPARE PARTS LIST FOR MW200 with 31i CNC

MMUSA PART NO.	DESCRIPTION	PART LOCATION	QTY.
Z07-49479-00	PROXIMITY SWITCH	CENTER SUPPORT	1
Z07-31816-00	LAMP (60HZ)	COOLANT SHIELD	2
MC9-13381-60	BRUSH	SHUTTER DOOR	2
Z06-62605-80	LIMIT SWITCH	REAR COVER	1
Z07-49476-00	PROXIMITY SWITCH	TURRET INDEX	2
Z07-68196-00	PHOTO SWITCH	UNLOAD CHUTE	1
Z07-47330-00	PROXIMITY SWITCH	HYD. SYSTEM	1
Z06-14327-80	PRESSURE SWITCH	WORK LOCATION SENSOR	1
Z07-42072-01	PUMP (COOLANT)	COOLANT PUMP	1
Z90-57565-00	ROTORY JOINT	CHUCK CYLINDER	1
T09-51032-50	GANTRY HEAD ASSY.	GANTRY HEAD	1
Z07-36853-00	SPINDLE BELT <i>(Need mach s/n)</i>	SPINDLE	1
Z07-36850-00	TIMING BELT <i>(Need mach s/n)</i>	SPINDLE	1