

SPARE PARTS LIST FOR MW50 with 31i CONTROL

MMUSA PART NO.	PARTS LIST NO.	DESCRIPTION	PART LOCATION	QTY.
T03-81000-40	T71-51A09-1+Z	Chuck Assy(A/B)	LOADER CHUCK	1
Z07-31684-00	T08-5115-003	RING(X)	LOADER CHUCK	1
Z06-10119-20	T08-5115-004	RING(O)	LOADER CHUCK	1
Z06-59623-00	T08-5115-009	PACKING	LOADER CHUCK	1
T05-13382-60	T25-1201-012	GUIDE	COOLANT SHIELD(L/R)	8
Z12-50088-00	T25-1201-024	RING(O)	COOLANT SHIELD(L/R)	1
Z08-09669-00	T25-1201-033	LAMP	COOLANT SHIELD(L/R)	1
Z06-49250-70	T25-1301-031	SWITCH (PRX)	SHUTTER(L/R),T.Fence	1
Z06-62605-80	T25-1401-016	SWITCH (LMT)	REAR COVER	1
Z08-06741-00	T25-3101-017	TIMING-BELT	X-AXIS(R)	1
Z07-31684-00	T71-4202-003	RING(X)	TURN AROUND CHUCK(L/R)	1
Z06-33946-60	T71-5105-007	SWITCH (PRX)	LOADER HEAD(L/R)	1
Z07-81723-00	T25-6501-042	PRESS. SWITCH-PARTS	HYD SYS	1
Z07-81726-00	T25-6501-043	PRESS. SWITCH-PARTS	HYD SYS	1
Z07-90765-00	T25-6501-044	PRESS. SWITCH-PARTS	HYD SYS	1
Z06-30667-30		SWITCH (LMT)	CONVEYER	1
Z07-68196-00		SWITCH (PH)	CONVEYER	1