

## SPARE PARTS LIST FOR M2044EZ B

MMUSA PART NO.	DESCRIPTION	QTY.
P01-23150-61	CARBIDE CHISEL EDGE	4
P01-23160-60	CARBIDE BUTTON	4
P05-20100-60	SPEED NUT	10
P05-20110-61	BALL TRANSFER	10
P66-12165-60	STOP ROD	5
P66-12178-60	SPRING	10
P67-12107-60	SLIDER	5
Z05-62093-00	FLEXIBLE TUBE	1
Z06-18824-70	JOINT(NIPPLE)	2
Z06-20439-10	JOINT(ELBOW)	2
Z06-27246-A0	HOSE	5
Z06-36432-10	HOSE	5
Z06-45374-A0	AIR FILTER ELEMENT	1
Z06-57321-30	REED SWITCH	1
Z06-76245-80	SPRING	2
Z07-49478-00	PROXIMITY SWITCH	1
Z06-49250-70	PROXIMITY SWITCH	1
Z07-49477-00	PROXIMITY SWITCH	1
Z07-04080-10	HOSE	5
Z07-15649-30	PROXIMITY SWITCH	1
Z07-28848-00	HOSE	5
Z90-25298-50	BALL TRANSFER	10
ZK6-90101-00	SLEEVE	2
ZK6-90106-00	NUT	2
ZK6-90221-00	INLET	2
ZK6-90223-00	SLEEVE	2
ZK6-90225-00	NUT	2
ZK9-21497-00	BALL TRANSFER	5
Z06-14832-60	HOSE	5
ZK9-22395-00	HOSE	5
Z06-13639-50	FUSE	3
Z06-25515-70	RELAY	2
Z06-30509-00	RELAY	2
Z06-41124-80	RELAY	2
Z06-44843-50	FUSE	3
Z06-66100-70	RELAY	2
Z07-02472-40	SWITCH POWER SUPPLY	1