

SPARE PARTS LIST FOR M5000

MMUSA PART NO.	DESCRIPTION	QTY
P01-23150-61	CARBIDE CHISEL EDGE	5
P01-23160-60	CARBIDE BUTTON	5
P05-20100-60	SPEED NUT	10
P05-20110-61	BALL TRANSFER	10
P38-79340-60	SPRING	8
P39-11200-61	2nd RAM SPRING	2
P39-12150-60	SPRING	20
Z05-62093-00	FLEXIBLE TUBE	1
Z90-55038-00	THEMO SWITH	2
Z06-32416-70	HOSE	1
Z06-39266-A0	ELBOW	1
Z06-45374-A0	FILTER ELEMENT	2
Z06-50372-00	AUTO SWITCH	2
Z06-90233-10	PROXIMITY SWITCH	2
Z07-49478-00	PROXIMITY SWITCH	2
Z07-49480-00	PROXIMITY SWITCH	2
Z07-49484-00	PROXIMITY SWITCH	2
Z07-49477-00	PROXIMITY SWITCH	2
Z52-50055-00	CARTRIDGE HEATER	3
Z90-36599-50	SPRING	20
Z90-55039-00	THEMO SWITH	2
ZK9-21270-00	FILTER ELEMENT	2
ZK9-22392-00	SYNFLEX HOSE	5
ZK9-22394-00	SYNFLEX HOSE	5
Z06-30509-00	RELAY	3
Z06-25515-70	RELAY	3
Z06-13639-50	FUSE	5
Z06-44843-50	FUSE	5
Z90-35638-52	MOTHER BOARD	1